

Patio Refurbishment & All Paving Maintenance



Case Study

Granite Driveway Entrance, Rochdale, Greater Manchester

Specialist paving contractor, CR Services, was asked to provide a solution for the failed grouting in this domestic cobbled driveway, which is situated high in the hills around Rochdale. The property is on a private road that is open to the elements, and is also shared by two farms who use it for daily access. Consequently, it is driven over regularly by heavy traffic and farm machinery. The entrance to the property from the road is composed of natural granite cobbles, which had previously been grouted using a cement based mortar, that had proved to be nowhere near up to the job and had failed.

This was no problem for CR Services, who advised replacing the failed grouting with Gftk's vdw 850+, a high performance, non-staining, 2-part epoxy paving mortar from NCC Streetscape. This is extremely tough and durable, has resistance to de-icing salts and freeze/thaw and is well capable of withstanding the heavy loading from such traffic.

The crew from CR Services raked out the old failed jointing and associated debris, and then applied Gftk's vdw 850+, finishing the job in double quick time. The owner is delighted with his refurbished driveway entrance that is now able to stand up to the traffic including heavy farm equipment on the road.

Domestic Driveways

Type of Stone
Granite

Type of Paving
Natural Cobbles/Tumbled Setts

Call CR Services

Office: **0161 905 3497**

Mobile: **0781 844 8330**

www.patiorefurbishment.co.uk



CRSERVICES