

# Patio Refurbishment & All Paving Maintenance



## Case Study

### Sandstone Patio, Alderley Edge, Cheshire

This private residence in Alderley Edge has a large sandstone patio and pathways covering an area of 180m<sup>2</sup>. Over the years these areas had become extremely dirty, with failed, sand and cement ointing, together with unsightly dark staining deposits on the natural stone slabs. The homeowners decided it was time to give the patio and pathways some care and attention and bring them back to their original beauty. They contacted specialist paving contractors CR Services who had successfully completed many such projects in the area.

CR Services recommended GftK's vdw 850+, which is a non-staining, 2-part epoxy paving joint mortar, supplied by NCC Streetscape, that is ideal for all types of natural stone paving. It is applied by wet slurry techniques, and will harden even in the cold and wet, so no delays in working due to inclement weather.

Prior to grouting, all areas were jet washed, the old failed cement jointing mortar was raked out and any green growth and black lichen spots were removed using NCC Black Spot and Green Growth Remover.

The crew from CR Services completed this large project quickly and efficiently, leaving the owners delighted with their patio which was now back looking not only as good as new, but in fact better with GftK high performance professional jointing.

#### Patios & Terraces

**Type of Stone**  
Sandstone

**Type of Paving**  
Slabs/Flags

**Call CR Services**

Office: **0161 905 3497**

Mobile: **0781 844 8330**

[www.patior refurbishment.co.uk](http://www.patior refurbishment.co.uk)



**CRSERVICES**