


# Patio Refurbishment & All Paving Maintenance



## Case Study

### Porcelain Patio Refurbishment, Croston, Lancashire

The owners of this property, in the picturesque village of Croston, in Lancashire, were desperate to find a solution to the problems they were encountering with their porcelain patio. It had only been down for two years and the pointing had already failed and been repointed twice, yet it was coming out again.

Having seen favourable reviews online, the homeowners consulted CR Services, who on inspection, instantly recognised the problem and offered a tough and lasting solution.

The patio had previously been pointed with typical single pack jointing compounds, which are not really suitable for jet-washing and use in the narrow joints commonly used with porcelain paving.

The solution from CR Services was to remove all the existing residual jointing compound, and replace the failed pointing with GftK vdw 815+, a high performance, 2-part epoxy paving mortar, that is stain free, fast and efficient to wet slurry apply. It is specifically designed for narrow joints, and importantly, can be safely jet-washed for ease of future maintenance.

CR Services also cleaned the patio with NCC Porcelain Aftercare cleaner to give an 'as new' look to the area, which the owners said was far better than when originally built and they were delighted!

#### Patios & Terraces

##### Type of Paving

External Porcelain Tiles

##### Call CR Services

Office: 0161 905 3497

Mobile: 0781 844 8330

[www.patior refurbishment.co.uk](http://www.patior refurbishment.co.uk)



**CRSERVICES**