

Patio Refurbishment & All Paving Maintenance



Case Study

Sandstone Patio & Pathways, Warrington, Cheshire

This large refurbishment project in Warrington comprised a traditional sandstone patio, plus pathways, and an ornamental brick and wood built gazebo area. These once attractive paved areas had only been laid around seven years ago but had now become unsightly because of cracked and failing sand and cement pointing mortar, together with dirt, grime, moss and lichen build-ups on the surfaces.

This was no problem to specialist paving contractors CR Services, who deal with such problems on a daily basis. They worked out a plan of action for the homeowners, and having been given the go-ahead, cut out the failing sand and cement mortar, jet-washed all surfaces and then applied NCC Black Spot & Green Growth Remover to clean up and remove the unsightly growths and dark staining deposits that had accumulated on the natural stone slabs.

The team from CR Services then re-pointed all areas with GftK vdw 850+ in natural colour. This is an extremely durable, 2-part epoxy based joint mortar, supplied by NCC Streetscape, to replace the failed cement mortar.

The homeowners were delighted with the finished result, with all paved areas looking like new, and which they can now jet wash regularly clean without fear of damage to the pointing.

Patios & Terraces

Type of Stone
Sandstone

Type of Paving
Slabs/Flags

Call CR Services

Office: **0161 905 3497**

Mobile: **0781 844 8330**

www.patior refurbishment.co.uk



CRSERVICES