Patio Refurbishment and Garden Maintenance



Case Study

Sandstone Patio, Southport, Merseyside

The owners of this property in Southport were looking for an experianced and reliable paving contractor to undertake the job of refurbishing their once beautiful and intrically laid out patio area. Over the years, the patio slabs had become ingrimed with dirt, dark lichen deposits had formed in the pores, and the grouting had failed.

Following online research they contacted CR Services who had undertaken many such jobs in the area, and who were more than happy to undertake this large project and bring it back to its once pristine condition.

The team at CR Services jet washed and thoroughly cleaned the dirty slabs and removed the lichen deposits using a specialist cleaning product supplied by NCC Streetscape. Any loose slabs were then reseated and levelled prior to replacing the failed grout.

This was done by using a unique, 2 part, high performance jointing system, which again was supplied by specialist suppliers NCC Streetscape. The skilled team at CR Services completed the job quickly and efficiently leaving the homeowners delighted with their beautuful again patio area, that is once again as good as the day it was originally laid.

Patios & Terraces

Type of Stone Sandstone

Type of Paving Slabs

Call CR Services
Office: 0161 905 3497
Mobile: 0781 844 8330
www.patiorefurbishment.co.uk

