

# Patio Refurbishment & All Paving Maintenance



## Case Study

### Porcelain Patio & Pathway, Knutsford, Cheshire

The homeowner of this property in Knutsford, was very proud of his porcelain tiled patio, which he regularly jetwashed to keep it clean and in pristine condition. Unfortunately, after only 18 months, he discovered that the original external tile grouting was not up to the job and that it was failing and being washed out, leaving unsightly gaps in many places. After extensive research, the owner contacted specialist paving contractors CR Services, and asked them for advice with regard to replacing the original pointing mortar with a tough and durable solution.

CR Services, together with their specialist material supplier NCC Streetscape, advised that GftK vdw 850+, an advanced, 2-part epoxy paving mortar was the ideal solution for this project with 6mm wide joints. GftK vdw 850+ paving mortar is non-staining, (staining is another problem when using cement based joint mortars), it can be regularly and safely jet-washed and can be installed in lower temperatures and wet weather - a huge advantage in the unpredictable British weather.

CR Services completed the refurbishment of the porcelain patio in very quick time. The homeowner was so delighted with the result, that he recommended CR Services to neighbours and family, who have since employed them to complete similar projects on their patios and paths.

#### Patios & Terraces

##### Type of Paving

External Porcelain Tiles (20mm)

##### Call CR Services

Office: 0161 905 3497

Mobile: 0781 844 8330

[www.patior refurbishment.co.uk](http://www.patior refurbishment.co.uk)



**CRSERVICES**