


Patio Refurbishment & All Paving Maintenance



Case Study

Sandstone Driveway & Patio, Eccles, Greater Manchester

The weather forecast for the December refurbishment of this large natural sandstone driveway and patio was cold and wet, but no problem at all for specialist paving contractors CR Services. They advised the use of GftK's vdw 850+ paving mortar from NCC Streetscape to replace the original mixture of single pack jointing compound and cement based grouting that were both now cracked and failing. GftK's vdw 850+, is a professional, 2-part, tough and durable, epoxy resin paving joint mortar that can be applied in the wet and cold weather, plus it is ideal for driveway use and can withstand loadings from the owner's two large vehicles.

The skilled team from CR Services removed the failed grouts, and re-bedded any loose slabs. They then cleaned all areas of the paving surfaces with NCC Black Spot & Green Growth Remover, which does exactly as it says on the tin, removing any unsightly green growth and difficult to clean and remove lichen blackspot deposits.

Although it rained for nearly the whole time through the application, CR Services completed the job, which was a total area of around 250m², quickly and right on schedule.

The homeowners were so pleased with the result that they recommended CR Services and GftK's vdw 850+ to a neighbour, who took their advice, and also then instructed CR Services to do a similar job to refurbish their garden patios and paving.

Domestic Driveways

Type of Stone
Sandstone

Type of Paving
Slabs/Setts

Call CR Services

Office: **0161 905 3497**

Mobile: **0781 844 8330**

www.patiorefurbishment.co.uk



CRSERVICES