

Patio Refurbishment & All Paving Maintenance



Case Study

Sandstone Driveway & Courtyard, Wilmslow, Cheshire

The large paved driveway and courtyard at this private residence in Wilmslow, covers an area of 125m², and is subjected to heavy domestic usage, as it is driven over daily by the family's three cars. Although the natural sandstone setts were still in good condition, the original cement based pointing was not up to the job, as the daily exposure to the dynamic movement of the family's vehicles had caused it to crack, break up and fail.

Following online research, the owners contacted CR Services, who advised that GftK's vdw 850+, a professional, 2-part epoxy paving mortar from NCC Streetscape, was the ideal solution for this project. It is tough and durable and can easily handle the stress and loadings associated with vehicle movements.

The skilled crew from CR Services firstly jetwashed the paving and removed the failing cement pointing. GftK's vdw 850+ was applied standing up by wet slurry techniques, with no additional tooling, so the job was completed quickly and efficiently.

The homeowner was delighted with his refurbished driveway and courtyard, which not only look magnificent again, but are in fact 'better than new', plus their driveway will easily handle the frequent dynamic loadings from the owners cars driving for many years to come.

Domestic Driveways

Type of Stone
Natural Sandstone

Type of Paving
Setts

Call CR Services
Office: **0161 905 3497**
Mobile: **0781 844 8330**

www.patior refurbishment.co.uk



CRSERVICES