


Patio Refurbishment & All Paving Maintenance



Case Study

Yorkstone Terrace, Macclesfield, Cheshire

The predominantly Yorkstone paved terrace of this beautiful, listed building in Macclesfield was in desperate need of refurbishment. The jointing mortar was cracked and failing, the slab surfaces were stained and ingrained with dirt, and there was an abundance of green growth on the slabs and in the joints, as well as an extensive amount of difficult to remove, lichen 'black spots' in the pores below.

CR Services were consulted and they advised that GftK's vdw 850+ epoxy resin based, paving joint mortar from NCC Streetscape was the ideal choice to durably repoint the failed joints, especially as they had various widths and depths. This is typical with historic natural Yorkstone paving, which always leads to problems of shrinkage and cracking when using traditional cement-based joint mortars.

After remedial works to remove the old jointing, the paving was jet-washed and then the surfaces treated with high performance NCC Black Spot and Green Growth Remover, which does exactly what it says on the tin!

The non-staining, vdw 850+ is wet slurry applied by squeegee, and it effectively self-compacts into the varying width joints, enabling CR Services to complete the job in double quick time, with the terrace now looking as good, in fact better than new.

Patios & Terraces

Type of Stone
Yorkstone

Type of Paving
Slabs/Flags

Call CR Services

Office: **0161 905 3497**

Mobile: **0781 844 8330**

www.patior refurbishment.co.uk



CRSERVICES