

Patio Refurbishment & All Paving Maintenance



Case Study

Indian Sandstone Patio, Warrington, Cheshire

Over the years these owners had had continuing problems with their beautiful terraced patios and pathways, all built in an attractive light coloured, natural Indian Sandstone. Unfortunately, the original traditional site-produced, sand and cement pointing had soon failed and then been repaired, this time with prebagged cement based jointing mortar.

However this had also failed and started to break up and fall out within a short period of time – and for the same reasons - sand and cement pointing is very sensitive to the vagaries of British weather.

Luckily for the the homeowners, they contacted CR Services who were able to give them a lasting solution to their problem.

After a thorough clean with NCC Black Spot & Green Growth Remover, the skilled team from CR Services re-grouted the patio using GftK's vdw 850+, a professional 2-part epoxy mortar supplied by NCC Streetscape that is not weather dependent for placing. The homeowners can now safely jetwash their patio without fear of failure.

So pleased were the owners that they booked CR Services to use the same process and treatment on their driveway.

Patios & Terraces

Type of Stone
Indian Sandstone

Type of Paving
Slabs/Flags

Call CR Services

Office: **0161 905 3497**

Mobile: **0781 844 8330**

www.patior refurbishment.co.uk



CRSERVICES