

# Patio Refurbishment & All Paving Maintenance



## Case Study

### Sawn Sandstone Patio & Pathway, Warrington, Cheshire

The sawn sandstone paving slabs used for the patio and pathways at this private residence in Warrington, enabled it to be constructed incorporating narrow 4mm joints, giving this natural stone patio a beautiful, clean appearance. Unfortunately, the single pack, 'standard' paving joint compound, that was used for the original pointing, had failed within the first 12 months.

Following online research, the homeowners contacted paving refurbishment specialists CR Services, who advised replacing the failed jointing with GftK vdw 815+, an advanced, 2-part epoxy paving mortar from NCC Streetscape. This was the ideal solution as GftK's vdw 815+ is stain free and is specifically designed to completely fill narrow joints, thus avoiding any voids forming that would threaten the structural integrity and lead to the joints failing.

Prior to grouting, the team from CR Services removed the failed grout and the patio slabs were jet-washed and thoroughly cleaned using NCC Black Spot & Green Growth Remover, to remove unsightly green staining and hard to remove lichen blackspot deposits.

The end result is a beautiful natural stone patio that is now tough and durable. It will withstand frost and jet-washing and last for many years into the future. Not just good as new, but better!

#### Patios & Terraces

**Type of Stone**  
Natural Sandstone

**Type of Paving**  
Sawn Sandstone Slabs

**Call CR Services**

Office: **0161 905 3497**

Mobile: **0781 844 8330**

[www.patior refurbishment.co.uk](http://www.patior refurbishment.co.uk)



**CRSERVICES**