


Patio Refurbishment & All Paving Maintenance



Case Study

Sandstone Patio, Warrington, Cheshire

The homeowner of this property in Warrington was so impressed with the new grouting carried out on her decorative sandstone patio by specialist paving contractor, CR Services, that she re-engaged them to refurbish and repoint her sandstone driveway.

The original compound grouting was failing so CR Services recommended Gftk's vdw 850+, a non-staining 2-part epoxy paving mortar from NCC Streetscape, that is extremely tough, durable and importantly on natural stone, non-staining. This professional jointing mortar is designed to withstand the extra rigours of vehicular traffic so is ideal for application on both patios and driveways. It is applied by wet slurry techniques, effectively self compacting into the joints with no additional tooling, so the whole operation is both quick and clean. A major advantage of vdw 850+ is that it can be applied in the wet and cold, so no waiting around for the weather - a huge plus in the UK!

Prior to grouting, the specialist team from CR Services first removed the old failed jointing and all areas were jet-washed and thoroughly cleaned using NCC Black Spot & Green Growth Remover, which removes unsightly green staining and hard to remove lichen deposits.

The homeowner was delighted with her finished patio and in particular her driveway, which she can now use safely without fear of inflicting any damage from daily vehicle movements.

Domestic Driveways

Type of Stone
Sandstone

Type of Paving
Slabs/Setts

Call CR Services

Office: **0161 905 3497**

Mobile: **0781 844 8330**

www.patior refurbishment.co.uk



CRSERVICES