


Patio Refurbishment & All Paving Maintenance



Case Study

Indian Sandstone Patio, Sale, Cheshire

This well-loved and well used back garden patio includes a decorative circular feature, also created in the same natural Indian Sandstone. Unfortunately it had seen better days and was looking somewhat tired and dirty with the original sand and cement grout failing in several places.

CR Services were asked to come up with a solution and proposed that the old failed grout should all be completely removed and then the stones should be jet washed and professionally cleaned using NCC Black Spot & Green Growth Remover. The patio would then be re-grouted using GftK's vdw 850+, 2-part high performance jointing system from NCC Streetscape.

The owners were delighted with this solution and asked the skilled team from CR Services to carry out the work, which they successfully completed quickly and efficiently.

The end result, a patio that was not only as good as new but better for the long term, so impressed the homeowners that they booked CR Services to do a similar job on their driveway, safe in the knowledge that the high performance pointing system from NCC Streetscape is designed to handle the extra stresses caused by vehicular traffic.

Patios & Terraces

Type of Stone
Indian Sandstone

Type of Paving
Slabs/Flags

Call CR Services

Office: **0161 905 3497**

Mobile: **0781 844 8330**

www.patior refurbishment.co.uk



CRSERVICES