

Patio Refurbishment & All Paving Maintenance



Case Study

Khandla Sandstone Patio, Merseyside *'Still Perfect after 7 Years'*

This natural Khandla Sandstone patio in Merseyside was laid new by CR Services, back in 2015, and grouted using a professional, high performance 2-part paving jointing mortar, which was supplied by NCC Streetscape. After seven years of frequent use for countless family events and frequent Alfresco dining, the paving and grouting were still sound and in perfect condition. However it had started to become unsightly with the surfaces needing a good clean, especially to remove green growth and hard to remove 'black spots', which are actually lichen deposits in the surface pores.

Having done such a good initial job, CR Services were contacted again by the owners and asked to advise on the best solution to clean, and then to undertake the works needed to restore the patios back to pristine condition. They recommended initial jet washing, followed by application of NCC Black Spot and Green Growth Remover, which does exactly as it says and removes unsightly green staining, as well as the difficult lichen blackspots.

Once again the homeowners are delighted with the work carried out by CR Services, and their Khandla Sandstone patio is back looking as good as the day it was originally laid - perfect again for those outdoor family events!

Patios & Terraces

Type of Stone

Khandla Sandstone

Type of Paving

Slabs/Flags

Call CR Services

Office: 0161 905 3497

Mobile: 0781 844 8330

www.patior refurbishment.co.uk



CRSERVICES